						Discipline	Sign		
		LOMBOK CFSPP FTP-2				Civil			
			JECT	Λί	Mechanical				
			CONTRACTOR DOCUME		Review	Electrical			
				IN I IVE AIFA	~	I&C			
		Log Date:				Support			
			In Comm. No :						
		А	Approved		Contractor				
		B Approved as Note				Record			
		С	''			Working Document			
		I	Information						
			APPROVAL DOES NO CONTRACTOR FROM RES FOR ERRORS AND DEVIA CONTRACT REQUIR	SPONSIBILITY ATIONS FROM	Distribution				
		By:	Date :	Date :					
		Log Out	Comm. No :						
		Owner: PT. PERUSAHAAN LISTRIK NEGARA (PERSERO) UNIT INDUK PEMBANGUNAN NUSA TENGGARA							
		Engineer : PT. PERUSAHAAN LISTRIK NEGARA (PERSERO) PUSAT ENJINIRING KETENAGALISTRIKAN							
		Contract No :							
		PLN Doc No :							
		Title : VISUAL INSPECTION REPORT FOR AREA C420							
		Purpose : ISSUE FOR APP			ROVAL				
Rev	Description		Prepared	Checked	Approved		Date		
0	For Approval		Benridho 😭	Rusnandi 🔌		Musato 47	17-April-2025		
PT. HANAZONO Engineering Indonesia We are always partner with you		PT. HANAZONO ENGINEERING INDONESIA		ITEM NO FOUIPMENT NAME	ESP PLATWORK FOR BOILER U LPP-10-F9-PO-239-R		OR BOILER UNIT 2		
Contractor :		Con	nsortium Of	PO.NO Doc. No :		LPP-10-F9	-ru-237-K		
		REKING Industrial Solutions GRUPA PBG		LPP-239-MEC-VS-284-V					

VISUAL INSPECTION REPORT FOR AREA C420

DOC. NO.:

LPP-239-MEC-VS-284-V

DATE

17-April-2025

BR

RSD

REV

0

APVD

APVD

MRS

REVISION HISTORICAL SHEET

Rev. No.	Date	Description
0	17-April-2025	Issue for Approval

PT. HANAZONO Engineering Indonesia RRFAKO VISUAL EXAMINATION REPORT Ne are always parties with usu GAS DISTRIBUTION LPP-239-MEC-VR-022-LOMBOK CFSPP FTP-2 (2x50 MW) Title Name DEVICES IN CONFUSOR Report No. Project Name **PROJECT** UNIT-2 BLOCK 1 04-Dec-24 PT. REKAYASA INDUSTRI Item No. C-420-01 Date Client. 1 OF 1 Job Code 2406 Page No. Drawing No. LPP-239-MEC-VG-151-V Type of Visual Heat Treatment Location ☑ Direct □ Before M N/A ☑ Shop □ Remote ☐ Field ☐ After Type of Work Surface Condition New New ☐ Repair ☐ Rework **☆** Ground ☐ Machined ☑ As Welded Joint No. / Result Type of Defect Remark Welding ID Welder WPS No. Acceptable Repair Identification LPP-239-MEC-VG-151-V 006/HEI/WPS/20 ٧ JT-01 AF-1307 HEI-WPS-AWS-FC-002 006/HEI/WPS/20 ٧ JT-02 RM-1206 HEI-WPS-AWS-FC-002

C: Crack UC: Under Cut

IR: Improper Weld Reinforcement

LF: Lack of Fusion

IP: Incomplete Penetration

P: Porosity, Other to be Described in Detail.

Reviewed / Wit

Approved by

Witnessed /

Reviewed by

We the undersigned certify that the statements in this record are correct and that the welds, were prepared and tested in accordance with the requirements of

* As per Client Spec.

BEMICIONO Dee 05

Examined By

M. Arts you xpl

Witnessed /

Reviewed by

HEI-QM-F-009